

Mecklenburg County

New Quarter Contractor Failure Rate Report

From October 1, 2019 to November 11, 2019

Contractor:

AL TYPE ELEC SERV CORP
104 RANKIN AVE
SUITE 109
MOUNT HOLLY, NC 28120

Grand Total:

Total Inspections:	6
Total Count as Failures:	0
Contractor Failure Rate:	0 %

For contractors with fewer than 7 inspections in a quarter, neither total failed nor a percentage of total failed inspections are reported because such measures based on a small number of inspections are sensitive to errors and hence could be misleading.

For contractors with 7 or more inspections in a quarter, with a confidence level of 99%, the probability that the reported inspection failure rate is within 2% of the true failure rate is at least 99.5%.

The data system has been tested and found to be highly reliable. For contractors as a group, over 46,000 of the 108,000 inspections performed during the 3rd quarter of 2006 were tested for accuracy in reporting, and no errors were found.

NOTE: Where this report refers to failed inspections, in no case are certificates of occupancy for any project issued until all detected code defects are corrected.